



Diving report for Arnarlax.

Date 12.02.18 Time : 19:45
 Location Hringsdalur
 Divers Valdimar, Fabian
 Assistants Maciek
 Most dive depth 36 meters
 Clients rep Valdi

Following checked/worked at:	Inside	Outside	mooring to	Frame /	Rope to	Other
	net cage	Netcage	cage/moori ng plates	buoys	anchors / cables	
	x					
Cage number	2					

Following factors checked while diving inside or outside of the netcage:

	Yes	No	Cause / repair
1 Was net good in sea	x		
2 Was a hole on net/abnormal tearing?		x	
3 Was dead fish collector in cage and working?	x		
4 Was dead fish in cage?	x		a pile of dead fish in the basket.
5 Was the net overgrown/where the most?		x	
6 Something else checked/worked at?	Net inspection.		
Other comments:			

Dead fish seen at the bottom by the basket. It was dark and visibility not good, so the picture was taken up close.

